

解説・写真集

目 次

口絵写真

1. 解説

- 1.1 はじめに 3
- 1.2 福井地震の前後 4
- 1.3 震災の概要と特徴 4
- 1.4 米極東軍総司令部による被害調査活動とその成果14
- 1.5 米極東軍総司令部による空撮写真17
- 1.6 報道関係機関による写真17

2. GHQ報告書の概要訳

- 2.1 GHQ報告書Vol. I21
- 2.2 GHQ報告書Vol. II30

3. 写真・地図集

- 3.1 震災前の福井市周辺47
- 3.2 震災直後からの被災地の状況55

4. 被災地域の垂直空撮写真151

- あとがき・参考資料190

Explanation and Photographs

contents

Frontispiece Photographs

Chapter 1 General Introduction

1.1 Introduction	3
1.2 Before and after the Fukui Earthquake	4
1.3 Introduction of the 1948 Fukui Earthquake Disaster	4
1.4 Activity and results of field investigation of the damage by GHQ, Far East Command	14
1.5 Aerial photographs by GHQ, Far East Command	17
1.6 Photographs in press	17

Chapter 2 Translation of Report by General Headquarters, Far East Command (*in Japanese*)

2.1 The Fukui Earthquake, Hokuriku Region, Japan	21
– Volume I, Geology – (<i>in Japanese</i>)	
2.2 The Fukui Earthquake, Hokuriku Region, Japan	30
– Volume II, Engineering – (<i>in Japanese</i>)	

Chapter 3 Photographs and Figures

3.1 View of Fukui City before earthquake	47
3.2 View of affected area due to earthquake	55

Chapter 4 Vertical Aerial Photographs of Affected Area

Acknowledgement	190
-----------------------	-----