

CONTENTS

| | page |
|--|------|
| Foreword | |
| I Summary and conclusions | 1 |
| II Introduction | 3 |
| A. Location | 3 |
| B. Purpose and scope | 3 |
| C. Acknowledgments | 5 |
| D. Japanese earthquake investigations | 7 |
| III The Earthquake | 7 |
| A. Eyewitness accounts | 7 |
| B. Destruction | 9 |
| C. Lessons | 12 |
| IV Geologic and seismic background | 13 |
| A. Japanese island arc | 13 |
| B. Tectonic divisions of Japan | 13 |
| C. Seismic zones of Japan | 14 |
| D. Deep focus earthquakes | 15 |
| E. Time distribution of large earthquakes | 15 |
| F. Seismic and tectonic relationships of the Fukui region | 15 |
| G. Geology of the Fukui region | 17 |
| 1. Topographic and geologic divisions | 17 |
| a. Fukui Plain | 17 |
| b. Takefu Plain | 20 |
| c. Tertiary mountains | 20 |
| d. Pleistocene sand hills | 21 |

| | page |
|--|------|
| 2. Faults | 21 |
| 3. Geologic history | 22 |
| V Seismic features of the Fukui earthquake | 22 |
| A. Time | 22 |
| B. Intensity | 22 |
| C. Epicenter | 25 |
| D. Seismograms | 27 |
| E. Aftershocks | 31 |
| F. Tsunami (seismic sea wave) | 33 |
| G. Cause | 33 |
| H. Forecasting | 33 |
| VI Geologic features of the Fukui earthquake | 35 |
| A. Geologic factors in the control of damage | 35 |
| 1. Damage boundaries | 35 |
| 2. Thickness of sediments | 35 |
| 3. Texture of sediments | 37 |
| 4. Exceptions | 37 |
| 5. Disrupted ground | 39 |
| B. Faults | 40 |
| 1. In alluvium | 40 |
| 2. In bedrock | 40 |
| 3. Inferred from surveys | 43 |
| 4. Neo Valley fault | 43 |
| 5. Faults in Fukui | 43 |
| 6. Misunoo fault | 48 |

| | page |
|---|------|
| 7. Kanazu fault | 48 |
| 8. Segoe fault | 49 |
| C. Vertical and horizontal movements | 52 |
| 1. Vertical movements | 52 |
| 2. Horizontal movements | 53 |
| D. Sand boils | 53 |
| 1. Definition | 57 |
| 2. Alignments | 60 |
| E. Fissures | 62 |
| F. Landslides and slump | 62 |
| 1. Distribution | 62 |
| 2. Roads | 74 |
| 3. Sand dunes | 74 |
| 4. Levees | 74 |
| G. Ground movements and man-made structures | 74 |
| H. Water table | 78 |
| VII References cited | 78 |
| VIII Glossary | 80 |
| IX Generalized geologic time scale | 81 |

TABLES

| | |
|---|----|
| 1. Comparison of the Fukui earthquake with other large earthquakes in Japan | 8 |
| 2. Casualties and destruction resulting from the Fukui earthquake | 10 |
| 3. Intensity scale used by Central Meteorological Observatory, Tokyo | 25 |

ILLUSTRATIONS

Plates (in envelope at back)

1. Damage and disruption caused by the Fukui earthquake, Japan, 28 June 1948, as related to the local geology (map)
2. Sand boils and fissures (mosaic of aerial photographs)

| Figures | page |
|---|------|
| 1. Index map, Fukui, Japan, and the island arcs | 2 |
| 2. Destruction in Fukui | 4 |
| 3. Photo coverage, Fukui earthquake | 6 |
| 4. Typical features of earthquake damage near Kanazu | 11 |
| 5. Major tectonic provinces of central Japan | 12 |
| 6. Principal earthquakes in Japan from 559 A.D. to 1948 | 14 |
| 7. Distribution of faults in Japan and earthquakes in the present period, 1847-1948 | 16 |
| 8. Epicenters of destructive earthquakes in the Hokuriku region | 18 |
| 9. Isoseismal map of Fukui earthquake, 28 June 1948 | 23 |
| 10. Intensity-distance curves of major earthquakes in Japan since 1923 | 24 |
| 11a,b,c Acceleration calculated from overturned objects | 26 |
| 12. Directional tilting of telephone poles | 28 |
| 13. Tokyo seismograms | 29 |
| 14. Sendai seismograms | 30 |

| | page |
|---|------|
| 15. Directions of initial ground motions in the Fukui earthquake as recorded at seismograph stations in Japan | 32 |
| 16. Protective effect of bedrock | 36 |
| 17. Idealized vertical section | 37 |
| 18a,b. Undamaged village of Mikuni, an exception | 38 |
| 19. Fault index, Fukui earthquake, Japan, 28 June 1948 | 41 |
| 20. Disrupted rice paddy | 42 |
| 21a,b,c. Disruption along railroad northeast of Kanazu | 42 |
| 22a,b,c,d,e,f. Faults in the city of Fukui, zone A | 44 |
| 23a,b,c,d,e. Faults in the city of Fukui, zone B | 46 |
| 24a,b,c,d. Minor fault and disruption north of Kanazu | 50 |
| 25. Changes in elevation, Fukui earthquake | 55 |
| 26. Tilting near Maruoka | 56 |
| 27. Horizontal movements, Fukui earthquake, Japan, 28 June 1948 | 57 |
| 28a,b,c. Sand boils and fissures west of Kanazu | 58 |
| 29. Fissures near Morita | 61 |
| 30a,b,c,d. Typical occurrences of fissures | 63 |
| 31. Disruption in sand dunes | 64 |
| 32. Landslides near Lake Kitagata | 65 |
| 33. Road disruption resulting from landslide | 65 |
| 34. Collapse along river bank in Kanazu | 65 |
| 35. Slumped railroad embankment | 66 |

| | page |
|---|------|
| 36. Buckling in surface of rice paddy | 66 |
| 37. Road slump along moat in Fukui | 66 |
| 38a,b,c. Disruption in fault zone E-C | 67 |
| 39a,b,c,d,e. Slumping in Fukui railroad yards | 68 |
| 40a,b. Weakened levees | 70 |
| 41a,b. Levees before and after floods | 72 |
| 42. Levee failure along faults | 75 |
| 43a,b,c. Damage to railroad tracks | 76 |
| 44. Typical damage to heavy structures | 77 |
| 45. Typical damage to lightweight structures | 77 |
| 46. Damaged bridge pier | 77 |